



Underwriters Laboratories Inc.®

TOMAR ELECTRONICS INC
MR T SIKORA
2100 W OBISPO AVE
GILBERT AZ 85233

Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your Assignment.

YCFT2 June 28, 1995
Component - Industrial Truck Accessories, Battery-Powered

TOMAR ELECTRONICS INC AU2049 (N)
2100 W OBISPO AVE , GILBERT AZ 85233

Flashing warning lights.

Models 470, 490, 495 followed by -1248 or 1280 may be followed by a suffix letter. Model 700 may be followed by G, followed by -120 or -1274, may be followed by suffix letters. Model 550-1274 may be followed by suffix letters.

Marking: Company name, model designation and rating.

See General Information Preceding These Recognitions.

For use only in equipment where the acceptability of the combination is determined by Underwriters Laboratories Inc.

Report: December 23, 1976.

Replaces AU2049 dated January 28, 1993.

148610003

Underwriters Laboratories Inc.®

D11/0029972

136

For information on placing an order for UL Listing Cards in a 3 x 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.

A not-for-profit organization dedicated to public safety and committed to quality service

333 Pfingsten Road
Northbrook, Illinois 60062-2096, USA
708/272-8800
Telex: 6502543343
FAX No. (708) 272-8129

1285 Walt Whitman Road
Melville, L.I., New York 11747-3081, USA
516/271-6200
Telex No. 6852015
FAX No. (516) 271-8259

1655 Scott Blvd.
Santa Clara, California 95050-4169, USA
408/985-2400
FAX No. (408) 296-3256

12 Laboratory Drive
P.O. Box 13995
Research Triangle Park,
North Carolina 27709-3995, USA
919/549-1400
Telex No. 4937928
FAX No. (919) 549-1842